




POWER ACTION®

Power action tools are your smart choice

AG720

No.	Part list	No.	Part list
1.	Down flange	23.	screw
2.	Upper flange	24.	Rotor
3.	Guard	25.	Bearing 607Z
4.	Spindle	26.	Bearing cover
5.	Anti-dust cover	27.	Wind guide
6.	Screw	28.	Screw
7.	Front cover	29.	Stator
8.	Bearing 6201Z	30.	Connection ring
9.	Circlip	31.	Motor housing
10.	Key	32.	Brush holder
11.	Big gear	33.	Carbon brush
12.	Circlip	34.	Brush cover
13.	Needle bearing HK0810	35.	Switch
14.	Gear box	36.	Cable press board
15.	Spindle lock shaft	37.	Screw
16.	Spring	38.	Cable sleeve
17.	Spindle lock button	39.	Cable
18.	screw	40.	Housing cover
20.	Pinion	41.	screw
21.	Bearing 6000Z		
22.	Bearing press board		